







TEST REPORT

CEPRI-EETC08-2019-0542 (E)

Client: Shenzhen Woer Electric Technology Co., Ltd.

Object: Termination with porcelain insulator for 64/110 kV

XLPE cable

Type: WYJZWY4 64/110 1×1600

Test Category: Type tests



R INDUSTRY QUALITY INSPECTION AND TEST
CENTER FOR ELECTRIC EQUIPMENT

Power Industry Quality Inspection and Test Center for Electric Equipment

Catalogue

1. Catalogue	1
2. Signature Page	
3. Test Results	3
4. Content	4
5. Appendix A Object Parameters	5
6. Appendix B The Main Test Devices	7
7. Appendix C Test Circuit Diagrams	8
8. Appendix D Waveform	9
9 Appendix F Identification of test cable	11

Test Report	Power Industry Quality Insp Center for Electric Ed	CEPRI-EETC08-2019-0542(E) Total 11 Page 2	
Client	Shenzhen Woen Electric Technology Co., Law	Manufacturer	Shenzhen Woer Electric Technology Co., Ltd.
Object	Termination with porcetain insulator for 64/110 kV XAPE cable	Туре	WYJZWY4 64/110 1×1600
Sampling procedure	在 拠 报 章 Taken by client self 章	Serial No.	EETC08-19/06/08-001
Test Category	Type tests	Date	2019.06.22~2019.08.26
Requirements	 GB/T 11017.3—2014 Power their accessories for rated voltage IEC 60840(Edition 4.0): 2011 accessories for rated voltages at -Test methods and requirements 	Power cables with the contract of the power cables with the contract of the c	6 kV) —Part 3: Accessories
		(2) 	THE PARTY OF THE P
Conclusion	The termination with porcelain in which is WYJZWY4 64/110 1×16 passed the type tests specified in G	son taken to test by I	ne chents own schillassacessian
Conclusion		600 taken to test by the B/T 11017.3—2014	and IEC 60840(Edition 4.0): 2011.
	which is WYJZWY4 64/110 1×16 passed the type tests specified in G In the event of any difference in r English version.	600 taken to test by the B/T 11017.3—2014	e report shall take priority over the
Note Compiled by:	which is WYJZWY4 64/110 1×16 passed the type tests specified in G In the event of any difference in r English version.	600 taken to test by the B/T 11017.3—2014 is meanings, the Chines	e report shall take priority over the

OM

一专

Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 3

Test Results

No.	Item	Requirements	Results	Evaluation
1	Partial discharge test at ambient temperature	No detectable discharge from the test assembly at 96 kV under a background noise	No detectable discharge was found from the test assembly at 96 kV under a background noise of 1.21 pC	Passed
2	Heating cycle voltage test	As per clause 1.2 of content in this report	Subjected to heating cycle voltage test, and heating cycle had been carried out 20 times	Passed
3	Partial discharge test at high temperature	No detectable discharge from the test assembly at 96 kV under a background noise	No detectable discharge was found from the test assembly at 96 kV under a background noise of 1.21 pC	Passed
4	Partial discharge test at ambient temperature	No detectable discharge from the test assembly at 96 kV under a background noise	No detectable discharge was found from the test assembly at 96 kV under a background noise of 1.21 pC	Passed
5	Lightning impulse voltage test	The test assembly shall withstand without failure or flashover 10 positive and 10 negative voltage impulses of 550 kV	No breakdown or flashover occurred on the test assembly at 10 positive and 10 negative voltage impulses of 550 kV	Passed
6	Power frequency voltage test after lightning finoulse voltage test	The test assembly shall be subjected to a power frequency voltage test at 160 kV for 15 min, and no breakdown of the insulation or flashover shall occurred	The test assembly have been subjected to a power frequency voltage test at 160 kV for 15 min, and no breakdown of the insulation or flashover was occurred	Passed
7	Power frequency voltage wet withstand test	The test assembly shall be subjected to a power frequency voltage test at 185 kV for 1 min, and no breakdown of the insulation or flashover shall occurred	The test assembly have been subjected to a power frequency voltage test at 185 kV for 1 min, and no breakdown of the insulation or flashover was occurred	Passed
8	Radio influence voltage test *	Radio influence voltage shall not exceed 450 µV at 1 MHz and 81 kV	The radio influence voltage measured is 19 μV at 1MHz and 81 kV	Passed
9	Pressure leak test	(250±10) kPa for 1 h, no leakage shall occur	(250±10) kPa for 1 h, no leakage occurred	Passed
10	Vacuum leak test	As per clause 1.7 of content in this report	The increased value of vacuum pressure did not exceed 10 kPa	Passed
11	Voltage test of pedestal insulator	The insulators shall be subjected to dc voltage of 25 kV for 1min and 10 positive and 10 negative impulse voltage of 37.5 kV, no breakdown or flashover shall occur	No breakdown or flashover occurred at dc 25 kV for 1 min and 10 positive and 10 negative impulses of 37.5 kV	Passed
12	Examination	As per clause 1.9 of content in this report	No signs of deterioration which could affect the system in service operation was found	Passe

Note: * According to Q / GDW 371—2009 Technical standard for power cable line with rated voltages from 10(6) kV up to 500 kV, the additional radio influence voltage test was performed after type tests as the requirements of the client.

Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 4

Content

1. Test methods

1.1 Partial discharge tests

The tests were carried out at ambient temperature and high temperature in accordance with GB/T 3048.12 and IEC 60885-3, There shall be no detectable discharge exceeding the declared sensitivity from the test object at 96 kV. The background noise is no more than 1.21 pC during these tests.

The test voltage shall be raised gradually to and held at 112 kV for 10 s and then slowly reduced to 96 kV and the partial discharge tests were carried out at 96 kV. At high temperature the test shall be performed on the sample at a conductor temperature of (95 100) °C. The conductor temperature shall be maintained within the stated temperature limits for at least 2 h.

1.2 Heating cycle voltage test

According to GB/T 11017/3—2014 and IEC 60840(Edition 4.0): 2011, the test assembly shall be heated by conductor current until the cable conductor reaches a temperature of (95~100) °C. The heating shall be applied for at least 8 h. The conductor temperature shall be maintained within the stated temperature limits for at least 2 h of each heating period. This shall be followed by at least 16 h of natural cooling to a conductor temperature less than or equal to 30 °C or within 10 K of ambient temperature, whichever is the higher. The cycle of heating and cooling shall be carried out 20 times. During the whole of the test period a voltage of 128 kV shall be applied to the sample.

1.3 Lightning impulse voltage test followed by a power frequency voltage test

The assembly shall be heated by conductor current only, until the cable conductor reaches a steady temperature of (95–100) °C. The conductor temperature shall be maintained within the stated temperature limits for at least 2 h.

The lightning impulse voltage shall be applied according to the GB/T 3048.13. The assembly shall withstand without failure or flashover 10 positive and 10 negative voltage impulses of 550 kV. After the lightning impulse voltage test, the test assembly shall be subjected to a power frequency voltage test at 160 kV for 15 min. No breakdown of the insulation or flashover shall occur.

1.4 Power frequency yoltage wet withstand test

The test shall be carried out in accordance with GB/T 16927.1 at a power frequency voltage of 185 kV for 1 min. no breakdown or flashover shall occur.

1.5 Radio influence voltage test

The radio influence voltage test on the sample shall be measured according to GB/T 11604 at 1 MHz with the applied voltage of 8 kV.

1.6 Pressure leak test

After the sample was installed, the sample shall be filled to a pressure of (250±10) kPa and maintained for 1 h at ambient temperature, no gas leakage shall occur at the sealed surface

1.7 Vacuum leak test

After the sample was installed, the sample at environment temperature vacuum to the residual pressure is 10 kPa and maintained for 1 h. At the end of the test, the increased value of vacuum pressure shall not exceed 10 kPa.

1.8 Voltage test of pedestal insulator

After the sample was tested, de voltage of 25 kV for 1min and impulse voltage test of 37.5 kV at 10 positive and 10 negative shall be performed on the insulators, no breakdown or flashover shall occur.

1.9 Examination

Examination of the accessories by dissection of a sample and, whenever possible, of the accessories by dismantling with normal or corrected vision without magnification shall reveal no signs of deterioration (e.g. electrical degradation, leakage, corrosion or harmful shrinkage) which could affect the system in service operation.

2. Test data

The values of lightning impulse voltages on the test assembly after heating cycle voltage test (at high temperature, 550 kV, $\pm 3 \%$ tolerance)

Ambient temperature: 33.0 °C Relative humidity: 52 % Barometric pressure: 0.1012 MPa

									u	nit: KV
Positive voltages	554	543	551	553	547	552	555	550	553	551
Negative voltages	551	548	562	561	550	549	549	548	548	547

Appendix A Object Parameters

A.1 Specification of sample

A.1.1 Sample state

The sample was manufactured in May, 2019, and was received on June 08, 2019 at Power Cable Quality Inspection Station of Power Industry Quality Inspection and Test Center for Electric Equipment, and it was in good condition without breakage.

A.1.2 Related information of sample

The material of connector is copper to, the material used for stress relief cone is Ethylene Propylene Diene Monomer (EPDM), the filler for the insulation in termination is polyisobutene, and the cable conductor is compacted with the connector by pressure.


A.1.3 Installation description

The sample to be tested has been installed by the manufacturer on a XLPE insulated single core cable with rated voltage 64/110 kV and having a cross-section of 1600 mm², the type and size of cable is ZB-YJLW02-Z 64/110 12/1600.

A.2 Photograph of sample

Tes


nspection and



Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 6

A.3 The dimensions of main construction of the sample tested



Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 7


Appendix B The Main Test Devices

Sequ- ence	Name of the equipment and instruments Type/Size	Serial No.	Full-scale range	Uncertainty / Accuracy	Verification / Calibration authority	Term of validity
1	RSZ-800-6-50 Corona-free series-resonant test system	204488 Rauipme	nt(0~800) kV	-		
2	KKF-800-5 Power frequency voltage divider	454485	(0∼800) kV	Class 1	National Meterage Center of High Voltage and Heavy Current	2020.07.21
3	Digital partial discharge detector	2013-023	(0.1~999) pC	10 %	National Meterage Center of High Voltage and Heavy Current	2019.11.04
4	CJDY-3000/600 Impulse voltage generator	01	(0~3000) kV		-	
5	CJDY-3000 HV divider for impulse voltage divider measurement	001	(0∼3000) kV	Class 1	National Meterage Center of High Voltage and Heavy Current	2020.07.07
6	HiAS1214 Digital impulse Voltage analysis system	28.71.0 (1) 20050512	(0~3000) kV	Class 3	National Meterage Center of High Voltage and Heavy Current	2020.05.20
7	272 Wet and dry bulb hygrometer	304	(0∼50) °C	General	Hubei Meteorological Metrology Station	2019.10.1
8	ESHS10 Radio influence voltage receiver	EMI-02	10kHz~3 GHz	±1 dB	Wuhan Measurement Station of CSIC	2020.08.0

Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 8

Appendix C Test Circuit Diagrams




There is no content below this page)

Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 9

Appendix D Waveform

D.1 Oscillograms of the lightning impulse voltages waveform




(There is no content below this page) POWOR

Power Industry Quality Inspection and Test Center for Electric Equipment


CEPRI-EETC08-2019-0542(E) Total 11 Page 10

D.2 Oscillograms of partial discharges

D.2.1 The background noise during partial discharge tests



D.2.2 The oscillogram of partial discharges at 96 kV(After heating cycle voltage test at high temperature)



Power Industry Quality Inspection and Test Center for Electric Equipment

CEPRI-EETC08-2019-0542(E) Total 11 Page 11

Appendix E Identification of test cable

Rated	voltage U ₀ /U(U _m) kV	64/110 (126) kV		
Construction	Core	Single core		
	Material	Copper TR		
	Construction	Milliken conductor		
Conductor	Cross section	1600 mm ²		
	Diameter	48.6 mm		
	Average thickness of conductor screen	1.9 mm		
for	Material	XLPE		
Insulation 1	Average thickness	16.0 mm		
t Cel	Diameter	86.3 mm		
Screen D	Average thickness of insulation screen	1.1 mm		
n an	Diameter of insulation screen	87. <mark>4</mark> mm		
Cushion and longitudinal water mpermeable barrier	Material	Three layers of semi-conducting elastic water impermeable swell tape		
Ins	Material	Aluminum		
Corrugated metallic.	Average thickness	2.3 mm		
sheath	Manufacturing technology of metallic sheath	Seam welded corrugated aluminum sheat		
	Material Material	PE		
Oversheath	Average thickness	6.6 mm		
C (**) C (*	Diameter	119.7 mm		
	Capacitance	270 pF/m		
Outer diameter of complete cable		119.7 mm		
	Marking of cable	扬州曙光电缆股份有限公司 ZB-YJLW02-Z 64/110 kV 1×1600 2019 年 5 月		